

Building Renewal Grant Application

Initial Submission Date:

Application ID: 728

Resubmittal Date:

Please provide as much of the requested information as possible. SFB staff will assist in developing required information that is not currently available.

District Name: Picacho Elementary District

Superintendent: Allen Rogers

Contact Person: Allen Rogers

Contact Phone Number: 520-466-7942

Contact Email: arogers@picacho.k12.az.us

School Site: Picacho School

Buildings:

Description of Problem

Please include a detailed description of the issues, as well as a description of and a copy of any professional studies, citations or reports from government entities, recommended solutions, and any cost information or estimates. If additional space is needed, please attach.

Two air conditioning systems have failed. One in the counselor's office and one in the 4th grade classroom. Estimated replacement cost of the units are \$10,000 each. The district is getting pricing at this time.

Project Category: HVAC

Are any of the above-described issues in buildings or part of buildings that are leased to another entity, including a district sponsored charter school? N

Available Funding

Current unencumbered building renewal fund balance (Fund 690):	\$0.00
Amount of Local funds planned for this project	\$0.00

Please outline any associated insurance coverage.

Liaison: Demland

ddemland@azsfb.gov

602-542-6567

Allen Rogers
Superintendent Printed Name

Allen Rogers
Superintendent Signature

9/17/13
Date

DATE

9/9/13

INVOICE

10046

DESERT SUN HEATING, COOLING & REFRIGERATION, INC.

P.O. BOX 12400 CASA GRANDE, AZ 85130
2656 S. STANFORD DR. CASA GRANDE, AZ 85194

PHONE 520-466-1489
FAX 520-466-3048

☐ COD ☐ CHARGE ☐ WARRANTY ☐ N/C ☐ RC

LICENSE # ROC243161
WWW.DESERTSUNHVAC.COM

BILL TO:

SERVICE RENDERED ADDRESS:

NAME Picacho School
COMPANY _____
ADDRESS _____
CITY, STATE, ZIP _____
PHONE _____

NAME _____
COMPANY _____
ADDRESS _____
CITY, STATE, ZIP _____
PHONE _____

MODEL <u>URMAA060CL10</u>	SERIAL <u>2A5657ADAAE349814008</u>	BRAND <u>RWD</u>	VOLTS	PHASE	1 3
MODEL	SERIAL	BRAND	VOLTS	PHASE	1 3

WORK PERFORMED <u>Found Static Pressure at 150 l/hg and 45 l/hg before turning unit on. Unit not equalizing. turned unit on. Low side at 30 psi and 175 High psi. Superheat at 52 and Subcool at 12. Unit has a back restriction also. Very likely it might have Freon leak too. Pressures are low but showing restricted too. Highly Recommend new unit, may even run into other issues if Repair.</u>					
DESCRIPTION	PART #	QUANTITY	AMOUNT		
* Need Price to Fix Restriction but Highly Recommend New Unit.					

TECH <u>Long</u>	START	FINISH	DIAGNOSTIC	
PRESSURES	HIGH	LOW	SUBCOOL	SUPERHEAT
CHECKS	SIZE	TEMP READING	FREIGHT	
AIR FILTER		RETURN	FUEL ADJUST.	
COND. MOTOR		SUPPLY	LABOR TOTAL	
EVAP MOTOR		SPLIT	MATERIAL TOTAL	
CONTACTOR		OUTSIDE	MATERIAL TAX	
PAN & DRAIN		WASHED COND	SUB TOTAL	
CAPACITOR	<input type="checkbox"/> SPLIT <input checked="" type="checkbox"/> PACK <input type="checkbox"/> HP <input type="checkbox"/> ELECT <input type="checkbox"/> GAS		TOTAL INVOICE	

EST. VALID FOR 30 DAYS

TERMS: NET 30

BALANCE(S) PAST DUE ACCRUE A 1.5% PER MONTH INTEREST CHARGE (18% ANNUALLY). IN THE EVENT THIS ACCOUNT IS REFERRED TO COLLECTIONS FOR NON-PAYMENT, BUYER AGREES TO PAY THE SELLER'S COLLECTION AGENCY, ATTORNEY'S FEES AND/OR COURT COSTS INCLUDING ALL FEES FOR APPEAL.

SIGNATURE X [Signature]